

## 1975 FJ40 2F – FJ40206447 - WORK HISTORY

1976 2F Engine: 2F-077633 – Completely Rebuilt (2019)

We spared no expense using OEM Toyota rebuild kit including bearings, seals, and gaskets, valves and oil pump. The only parts that are not Toyota are the pistons and rings. The head was milled to perfection and .30 over dome pistons and rings were installed by Bob Hollingsworth. Engine was built by Bob Hollingsworth at TPI in Nashville, TN.

### Braking System

Emergency Brake – rebuilt (2019)  
Disc Brake Conversion (new front axle) (2019)  
Soft Lines, Calipers, Pad, Discs (2019)  
Brake Booster brand new OEM (2019)  
Brake Master Cylinder brand new OEM (2019)

### Mechanical

Radiator OEM – installed brand new (2018)  
Temp Sender OEM – installed brand new (2018)  
Radiator hoses – installed brand new (2018)  
Vacuum Hoses – all (2019)  
Water pump/gasket OEM – installed brand new (2018)  
Thermostat/gasket OEM – installed brand new (2018)  
Fuel pump/gasket OEM – installed brand new (2018)  
Alternator – Bosh (2019)  
Voltage Regulator ????? (2018)  
Oil Pressure Sender OEM – installed brand new (2018)  
Fuel Filter OEM – installed brand new (2018)  
Starter – installed new/refurbished (2018)  
Wires/Plugs/Cap/Rotor/Air Filter/Oil Filter – OEM installed brand new (2018)  
Ignition Coil OEM – installed brand new (2018)  
2 belts – installed brand new (2018)  
Tie Rod Ends – installed Japanese 555 Brand (2018)  
Gas Tank – brand new non-OEM installed (2018)  
Clutch Master & Slave Cylinder OEM – brand new installed (2018)  
Heater valve OEM – brand new installed (2018)  
Timing cover gasket OEM – brand new replaced (2018)  
Front main seal OEM – brand new replaced (2018)  
Front Pinion Seal – front replaced (2018)  
All Fluids – synthetic (2018)

### Non Mechanical

Windshield w/rubber gasket – replaced (2018)  
Front & Rear bumpers OEM – replaced brand new (2018)  
Dash Pad –OEM – replaced brand new (2018)  
Review View Mirror OEM – replaced brand new (2018)  
Roof refinished and new OEM gasket – replaced (2018)  
Light bulbs – replaced all (2019)  
New Speedometer Cable (2019)  
Seat Belts - Shoulder (2019)  
Muffler OEM (2019)